

HABS  
ND,  
42-GORI  
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Daniel Winter House  
Goodrich Vicinity  
Sheridan County  
North Dakota

HABS No. ND-18

Documentation: 7 sheets (including site plan and elevations 1983)  
8 exterior photos (1983)  
6 interior photos (1983)  
10 data pages (1983)  
1 field record (including field photographs and notebook  
1983)

Bras Muessig and Angela J. Schiller, Photographers, September 1983

ND-18-1 VIEW LOOKING WEST  
ND-18-2 VIEW LOOKING NORTHWEST  
ND-18-3 VIEW OF SOUTH FRONT  
ND-18-4 VIEW OF EAST SIDE  
ND-18-5 VIEW OF NORTH SIDE  
ND-18-6 VIEW OF WEST SIDE  
ND-18-7 DETAILED VIEW OF ROCK AT BASE  
ND-18-8 DETAILED VIEW OF CEILING AND ROOF JOISTS AT SILL PLATE  
ND-18-9 INTERIOR VIEW OF KITCHEN LOOKING AT SOUTH AND WEST WALL  
ND-18-10 INTERIOR VIEW OF KITCHEN LOOKING WEST INTO LIVING/SLEEPING ROOM  
ND-18-11 INTERIOR VIEW LOOKING EAST FROM LIVING/SLEEPING ROOM TO KITCHEN  
ND-18-12 DETAIL OF INTERIOR WINDOW LOOKING WEST  
ND-18-13 DETAIL OF DESIGN OF CEILING IN LIVING/SLEEPING ROOM  
ND-18-14 VIEW LOOKING WEST INTO SECOND FLOOR ROOM